Make	Lotus	Since Oct 2010, ATS silent discs are used for			Standard		Silent LSD		Carbon LSD (1st generation)					
				D & Deftforce L	SD		T(at the end of part #) -reinforced internal			New generation metal LSD w/o chattering			Ultra smooth and quiet operation	
							gears.		noise. 82mm/87mm disc - 45 & 55 degree cam 95mm/109mm disc - 45 & 60 degree cam					
							D20 - Stronger LSD w/ 20 internal discs							
Model	Year	Chassis	Engine	Trim	Section	Replace-	Parts number	Retail price	Note	Parts number	Retail price	Note	Parts number	Retail price Note
						ment Diff	A; 2 way, B: 1.5 way, C: 1 way		A: 2way, B: 1.5 way, C: 1 way		A: 2 way, B: 1.5 way, C: 1 way			
Elise			К18		М		RLMB8710	\$1,503.43		SLMB8710	\$1,578.00		CLMB8710	\$1,972.86
							RLMC8710	\$1,627.71	1 way	SLMC8710	\$1,702.29	1 way	CLMC8710	\$2,112.14 1 way
Exige			2ZZ-GE		M		RLMB8730T	\$1,122.29	#1	SLMB8730T	\$1,196.86	#1	CLMB8730T	\$1,564.29 #1
							RLMC8730T	\$1,246.57	#1, 1way	SLMC8730T	\$1,321.14	#1, 1way	CLMC8730T	\$1,703.57 #1, 1way

							Carbon Hybrid		Carbon LSD Spec		Carbon LSD Spec	Carbon LSD Spec III, Spec IV		
							Higher initial torque 12	kg - 15kg	Ultra high response		Ultra high response Higher initial torque 15kg (III), 20kg (IV)			
							Last 4 digits indicates the	ne combination and	Higher initial torque 10kg to	11kg				
							the initial torque							
Model	Year	Chassis	Engine	Trim	Section	Replace-	Parts number	Retail price Note	Parts number	Retail price Note	Parts number	Retail price Note		
						ment Diff	ff <mark>A; 2 way, B: 1.5 way, C: 1 way /</mark>		A: 2way, B: 1.5 way, 0	C: 1 way	A: 2 way, B: 1.5 way, C: 1 way			
Elise			K18		М		CLMB8710-HB42	\$1,880.00						
							CLMC8710-HB42	\$2,019.29 1 way						
Exige			2ZZ-GE		М		CLMB8730T-HB42	\$1,471.43 #1			CLMB87G30T III	\$1,564.29 #1		
											CLMB87F30T IV	\$1,564.29 #1		
							CLMB8730T-HB42	\$1,610.71 #1, 1way			CLMC87G30T III	\$1,703.57 #1, 1way		
											CLMC87G30T IV	\$1,703.57 #1, 1way		

Note

#1: For a vehicle with an open differential, Toyota ring gear bolt 90105-11040 x8 is required